

Traveler Title:

Booster Correction Multipole Magnet Assembly

Specification No:

5520-TR-333819

Revision:

J

DR No:

4537

Step No:

4.3

Drawing No:

445210

Routing Form No:**Serial No:**

BMA064

Rework ID:

0

Discrepancy Description:

Traveler instructs to, Acquire 12 BMA Coils with Vendor Traveler/Inspection Reports. You need to acquire 8 ea BMA-C1-XXX coils, 2 ea, BMA-C2-XXX, and 2 ea BMA-C3-XXX coils.

Coils used at the 12 "O" clock and 6 "O" clock should be BMA-C2 type coils and serialized as such.

Actual coils used at the 12 "O" clock and 6 "O" clock position are 12 "O" clock BMA-C3-028 and at the 6 "O" clock position BMA-C3-118, they have been converted to C2 type coils.

Originator:

Dennis Gaw

Date:

7/25/2008 2:49:30 PM

Cause of Nonconformance:

No BMA-C2 type coils available for this magnet.

Responsible Authority:

Dennis Gaw

Date:

7/25/2008 2:49:30 PM

Disposition:

Use as is
Disposition verify notes: Assembly has proceeded.

Responsible Authority:

Sasha Makarov

Date:

8/1/2008 1:42:43 PM

Corrective Action to Prevent Recurrence:

None
Disposition verify notes: None.

Responsible Authority:

Sasha Makarov

Date:

8/1/2008 1:42:43 PM

Corrective Action/Disposition Verified By:

Dennis Gaw

Date:

8/19/2008 2:08:03 PM

Will Configuration be affected?: ☐ YES ☒ NO

Identified problem area:

☒ Material ☐ Manpower ☐ Method ☐ Machine ☐ Measurement

Reviewed By:

Bob Jensen

Date:

8/20/2008 8:43:22 AM